Oil Field Environmental Incident Summary

Responsible Party: Deer Valley Trucking **Well Operator:** HRC OPERATING, LLC

Well Name: RASMUSSEN 1-21-16H

Field Name: STRANDAHL Well File #: 20844

Date Incident: 8/10/2014 Time Incident: 08:45 Facility ID Number:

County: WILLIAMS Twp: 157 Rng: 102 Sec: 21 Qtr: SW SE

Location Description: Constructed well site near tank battery load lines

Submitted By: Kelly Grimm Received By:

Contact Person: Rick Thompson

310 Airport Rd Suite 700

Williston, ND 58801

General Land Use: Well/Facility Site

Affected Medium: Well/Facility Soil

Distance Nearest Occupied Building:1 MileDistance Nearest Water Well:1 Mile

Type of Incident: Truck Overflow

Release Contained in Dike: Yes - On Constructed Well Site Reported to NRC: No

Spilled Units Recovered Units Followup Units

Oil

Brine 2 Barrels 2 Barrels

Other

Description of Other Released Contaminant:

NA

Inspected: Written Report Received: Clean Up Concluded:

Risk Evaluation:

None

Areal Extent:

Contained on constructed well pad

Potential Environmental Impacts:

No impacts to surface/ground water. Impact limited to well site scoria/gravel

Action Taken or Planned:

Fluid immediately sucked up and impacted scoria scraped up.

Wastes Disposal Location: E&P approved disposal

Agencies Involved:

Updates

Date: 8/13/2014 Status: Reviewed - Assigned to Other Agency Author: Roberts, Kris

Updated Oil Volume:

Updated Salt Water Volume:

Updated Other Volume:

Updated Other Contaminant

Notes:

Release, due to a truck overflow, remained on location according to the report. NDIC retains oversight.